



Hill Laboratories

Auckland

Client Number 9342

28 Heather Street, Parnell, Auckland, 1052

Telephone 0508 445-5522

www.hill-laboratories.com

Authorised Representative

Ms Leisle Jacobsen
Quality Manager - Lead Auditor
Private Bag 3205
Waikato Mail Centre
Hamilton 3240
New Zealand

Programme

Chemical Testing Laboratory

Accreditation Number 1167

Initial Accreditation Date 11 May 2016

Conformance Standard

ISO/IEC 17025:2017

General requirements for the competence of testing and calibration laboratories

Laboratory Services Summary

2.64 Asbestos

Key Technical Personnel

Miss Mahaleel (May) Alfante	2.64(a)(b)
Mrs Alexa Badenhorst	2.64(a)(b)
Miss Danielle Carter	2.64(a)(b)

Operations Manager
Authorisation:

Issue 17

Date:22/08/23

Page 1 of 2



Hill Laboratories
Chemical Testing Laboratory
SCOPE OF ACCREDITATION

Accreditation Number 1167

2.64 Asbestos

(a) Identification

Bulk identification of asbestos using polarised light microscopy (PLM)


AS 4964:2004 Method for the Qualitative Identification of Asbestos in Bulk Samples

(b) Fibre Counts

Analysis

Determination of air-borne asbestos fibre counts on membrane filters

National Occupational Health & Safety Commission: 3003(2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (2nd Ed)

Operations Manager Authorisation:		Issue 17	Date:22/08/23	Page 2 of 2
--------------------------------------	---	----------	---------------	-------------